



Comfort. Under control.

11-21 CULVERS - PUNTA GORDA, FL

Project Issue Information

Issue Name : AC2 is above designed cfm

Description : RTU2 is currently at 7328 out of a designed 5000 cfm. Cannot turn down due to motor sheave being stuck in place.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 11/23/2022 - Ian Fuller - National TAB

Project Issue File Details



FuseIT3549d9df088541d...



Comfort. Under control.

11-21 CULVERS - PUNTA GORDA, FL

Project Issue Information

Issue Name : RTU#1 has high flow

Description : AC1 has 7649 cfm out of a designed 5200 cfm. Cannot turn down RTU cfm due to motor sheave stuck in place.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 11/23/2022 - Ian Fuller - National TAB

Project Issue File Details



FuselTd9c3ba2ffc48479...



Comfort. Under control.

11-21 CULVERS - PUNTA GORDA, FL

Project Issue Information

Issue Name : RTU2 motor access door is damaged.

Description : Door is bent and is starting to shear on the sides.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 11/23/2022 - Ian Fuller - National TAB

Project Issue File Details



FuselT1f2209c3b98c46e...



FuselTd83cb84a02a146c...



Comfort. Under control.

11-21 CULVERS - PUNTA GORDA, FL

Project Issue Information

Issue Name : RTUOA IS MISSING OA filters

Description : Needs two outside air filters sized 23X14 to protect dampers.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 11/23/2022 - Ian Fuller - National TAB

Project Issue File Details



FuselTea3e59d302ae408...