

**Report By:**

National TAB  
105 Stone Village Drive  
Fort Mill, SC 29708



**Report: Deficiency Report**  
**Function: Test, Adjust, & Balance**  
**Date: 10/08/2025**  
**Completed By: National TAB**

**PROJECT**  
**10-06-25 QT #1121 EASLEY, SC**

4855 CALHOUN MEMORIAL HWY

EASLEY, SC

**Client**

QUIKTRIP  
4705 SOUTH 129TH EAST AVENUE  
TULSA, OK 74134

## Issue List

- EF-1 not working
- EF-2 no speed controller
- RTU 2 & 3 economizers don't work
- RTU-3 wrong diffusers



**10-06-25 QT #1121 EASLEY, SC**

**Project Issue Information**

**Issue Name :** EF-1 not working  
**Description :** When attempting to turn on the fan the motor began to smoke.  
**Created By :** National TAB                      **Assigned To :** National TAB - Brianna Biggs  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** EF1  
**Originated Date :** 10/08/2025 - Christian Moller - National TAB

Project Issue File Details



10/08/2025




10-06-25 QT #1121 EASLEY, SC

Project Issue Information

**Issue Name :** EF-2 no speed controller  
**Description :** EF-2 does not have a speed controller, airflow is less than design. Left low.  
**Created By :** National TAB                      **Assigned To :** National TAB - Brianna Biggs  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** EF2  
**Originated Date :** 10/08/2025 - Christian Moller - National TAB

Project Issue File Details



10/08/2025



10/08/2025



**10-06-25 QT #1121 EASLEY, SC**

**Project Issue Information**

**Issue Name :** RTU 2 & 3 economizers don't work  
**Description :** RTU 2&3 economizers do not work. When using the dial on the economizer itself as well as the Emerson board the flaps do not open.  
**Created By :** National TAB                      **Assigned To :** National TAB - Brianna Biggs  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 10/08/2025 - Christian Moller - National TAB

Project Issue File Details



10/08/2025



10/08/2025



**10-06-25 QT #1121 EASLEY, SC**


**Project Issue Information**

**Issue Name :** RTU-3 wrong diffusers  
**Description :** The new diffusers for RTU-3 are not the correct ones. The correct ones are Titus 300F's with deflection blades. Unit was still balanced to design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Brianna Biggs  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :** RT-3  
**Originated Date :** 10/08/2025 - Christian Moller - National TAB

Project Issue File Details



10/08/2025



10/08/2025