

PlanGrid Task Report - Dec 4, 2024

Prepared by Will T

Dec 4, 2024

Description

1 task in this report.

#43 [UNIT 999] [NEW] (MISC) AC-3 Alarmed / Missing Sensors

Status

In Review

Assignees

enos.colvin@buffaloconstruction.com

Type

Issue

Watchers

enos.colvin@buffaloconstruction.com

Description

AC-3 is alarmed for Return air Temperature/ Humidity. Return sensors are not installed on this unit and unit is displaying wild readings. Trane was notified, recommend they are contacted again as to absence of sensors and how this impacts operation.

Created

Sep 24, 2024 9:56 AM
mmcdonnell@nationaltab.com

Last Updated

Nov 25, 2024 7:46 AM

Comments

I re-looked at this error code today. There is nothing I can do for it. The unit needs to be looked at by Trane and the circuit board more than likely reprogrammed. The fault code is for sensors that do not exist in this unit. Per Jasen Cox with Xtreme Comfort.


Giovanni Giorcelli Nov 25, 2024

Photos

L05649_Blairs Ferry Rd FSU (IA)

3241 Blairs Ferry Road Northeast, Cedar Rapids, Iowa

L1020005649



IMG_0200
Michael McDonnell
Sep 24, 2024 9:59 AM




IMG_0199
Michael McDonnell
Sep 24, 2024 9:59 AM

L05649_Blairs Ferry Rd FSU (IA)

3241 Blairs Ferry Road Northeast, Cedar Rapids, Iowa

L1020005649



IMG_0349

Michael McDonnell

Sep 24, 2024 9:58 AM