

PlanGrid Task Report - Feb 8, 2024

Prepared by Ian Fuller

Feb 8, 2024

Description

4 tasks in this report.

Contents

#123 [CNTL 098] Ansul pull labeling.	2
#122 [CNTL 107] (MISC) Missing Ansul pull stations.....	3
#120 [EXHA 127] Grease exhaust duct is not supported.....	4
#118 [UNIT 168] Equipment not secured properly.	5

L04916_Princeton Woods FSU (Dumfries, VA)

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200

#123 [CNTL 098] Ansul pull labeling.

Status

Open

Start Date

Feb 6, 2024

Sheet

M-301

Type

Planned Work

Created


Feb 6, 2024 4:16 PM
ianf@nationaltab.com

Description

Label all Ansul pull stations for which hoods they serve.

Last Updated

Feb 7, 2024 10:44 AM



Photos



Missing Ansul Label

Ian Fuller

Feb 6, 2024 4:32 PM

L04916_Princeton Woods FSU (Dumfries, VA)

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200

#122 [CNTL 107] (MISC) Missing Ansul pull stations

Status

Open

Start Date

Feb 6, 2024

Sheet

M-301

Type

Planned Work

Created


Feb 6, 2024 4:16 PM
ianf@nationaltab.com

Description

Ansul pull stations are not yet installed at locations designated

Last Updated

Feb 7, 2024 10:44 AM




Photos



Missing Ansul 1

Ian Fuller

Feb 6, 2024 4:32 PM



Missing Ansul 2

Ian Fuller

Feb 6, 2024 4:32 PM

#120 [EXHA 127] Grease exhaust duct is not supported.

Status
Open

Start Date
Feb 6, 2024

Sheet
M-401


Type
Planned Work

Created
Feb 6, 2024 4:16 PM
ianf@nationaltab.com

Description

Exhaust duct for EF#1 is to be supported per kitchen hood exhaust fan detail on 6'0" centers.

Last Updated
Feb 7, 2024 10:45 AM



Photos



Duct Support Spacing

Ian Fuller

Feb 6, 2024 4:33 PM



Grease Duct Supports

Ian Fuller

Feb 6, 2024 4:33 PM

#118 [UNIT 168] Equipment not secured properly.

Status

Open

Start Date

Feb 6, 2024

Type

Planned Work

Created

Feb 6, 2024 4:16 PM
ianf@nationaltab.com

Description

Equipment not secured properly to curb, high wind/ seismic clips not installed. Mechanical stated that unit package did not come with seismic clips.

Last Updated

Feb 7, 2024 10:43 AM

Photos



Missing Seismic Clips

Ian Fuller

Feb 6, 2024 4:36 PM