

# PlanGrid Task Report - Feb 14, 2024

Prepared by Ian Fuller

Feb 14, 2024

## Description

4 tasks in this report.

## Contents

#123 [CNTL 098] Ansul pull labeling. ....	2
#122 [CNTL 107] (MISC) Missing Ansul pull stations.....	4
#120 [EXHA 127] Grease exhaust duct is not supported.....	6
#118 [UNIT 168] Equipment not secured properly. ....	8

**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200

**#123 [CNTL 098] Ansul pull labeling.**

**Status**

Open

**Start Date**

Feb 6, 2024

**Sheet**

M-301

**Type**

Planned Work

**Created**

Feb 6, 2024 4:16 PM  
ianf@nationaltab.com

**List**

4.9 Mechanical Test &  
Balance


**Last Updated**

Feb 9, 2024 9:53 AM

**Description**

Label all Ansul pull stations  
for which hoods they serve.

**Photos**



**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Missing Ansul Label

**Ian Fuller**

Feb 6, 2024 4:32 PM

---

**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200

**#122 [CNTL 107] (MISC) Missing Ansul pull stations**

**Status**

Open

**Start Date**

Feb 6, 2024

**Sheet**

M-301

**Type**

Planned Work

**Created**

Feb 6, 2024 4:16 PM  
ianf@nationaltab.com

**List**

4.9 Mechanical Test &  
Balance


**Last Updated**

Feb 9, 2024 9:53 AM

**Description**

Ansul pull stations are not yet installed at locations designated

**Photos**



**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Missing Ansul 1

**Ian Fuller**

Feb 6, 2024 4:32 PM



Missing Ansul 2

**Ian Fuller**

Feb 6, 2024 4:32 PM



**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Duct Support Spacing

**Ian Fuller**

Feb 6, 2024 4:33 PM



Grease Duct Supports

**Ian Fuller**

Feb 6, 2024 4:33 PM

**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200

**#118 [UNIT 168] Equipment not secured properly.**

**Status**

Open

**Start Date**

Feb 6, 2024

**Sheet**

M-250

**Type**

Planned Work

**Created**

Feb 6, 2024 4:16 PM  
ianf@nationaltab.com

**List**

4.9 Mechanical Test &  
Balance


**Last Updated**

Feb 9, 2024 9:56 AM

**Description**

Equipment not secured properly to curb, high wind/ seismic clips not installed. Mechanical stated that unit package did not come with seismic clips.

**Photos**



**L04916\_Princeton Woods FSU (Dumfries, VA)**

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Missing Seismic Clips

**Ian Fuller**

Feb 6, 2024 4:36 PM

---