



### Sarpinos NLW inspection

#### CheckList Information

**Name :** FIV **Status :** Not Completed  
**Assigned Organization :** National TAB **Asset :**  
**Requesting Organization :** National TAB

#### CheckList Item Details

Brackets and Shelf Supports

12/15/2023

Comment

1: Middle support bracket not installed. 2: s/s shelf not secured to the wall. 3: bracket under the wire shelf needs to be mounted under the triple sink



D3EED680\_2DA9\_4B27\_B  
91E\_3893A26DC142.jpeg



1DDF53A0\_6C7E\_4CC3\_9  
7BD\_94BB8252B8A7.jpeg



5CDAFBB3\_7CE8\_4008\_B  
46A\_82B716FC3FC0.jpeg

Cove Base & Seal

12/15/2023

Comment

1: Cove base not complete. 2: Cove base not complete 3. all cove bases need to be sealed especially in triple sink and mop sink area



A344DBB6\_F800\_4292\_8  
A23\_9527A16AF9B2.jpeg



74A0416A\_872B\_444C\_B  
DBE\_D978DC8F5BA5.jpe  
g



6F44EBA3\_FA68\_4FCC\_8  
88B\_OC3BD540E8D6.jpeg

S/S Trim

Comment

1: Corner trim is not professionally terminated. 2: Ceiling grid around trip is not professionally terminated. 3: end wall caps have large gaps



2DD91F65\_4DE5\_4DC0\_B  
368\_1FA81EDEFDC1.jpeg



FFEDE0C3\_D5E7\_467E\_A  
4BA\_911FBE1E049D.jpeg



CDB49F5A\_C600\_48C7\_9  
ED9\_0DE1B3D2695D.jpe  
g

SS Trim

Comment

1: Corner trim is not professionally terminated. 2: s/s trim is bent. 3: Door trim not sealed



9C167E58\_4F73\_47DA\_8  
A88\_5AAF3257A644.jpeg



86BD6276\_3F6C\_40FD\_A  
FAD\_F5102E258050.jpeg



3F3C77A1\_467B\_4561\_B  
C26\_8F76BAF32625.jpeg

Sinks / Caulk

Comment

1: Oversized FRP holes cut for sink drain and not sealed. 2: Oversized FRP holes cut for water lines and not sealed 3: Sinks not caulked to wall



5E1AD0F1\_47D1\_48AA\_  
A423\_CB37A2CD7447.jp  
eg



715ACEE5\_4BAF\_453B\_9  
FC5\_3B1D318655F1.jpeg



9A576D1D\_70B6\_49A0\_  
A63D\_A29DCF4F5996.jpe  
g

Window Seal and S/S end cap seal

Comment

1: Window seal gap needs to be sealed



234CF478\_81A9\_4DA7\_9  
DB6\_D0BDF1D783C0.jpe  
g

Mop Sink Area

Comment

All FRP and Base cove areas around wet areas need to be sealed



4ACFBABE\_4D38\_4DC7\_  
BE50\_D9F795F95CC2.jpe  
g



435458D0\_35D9\_4C27\_B  
910\_1F07DC81A393.jpeg

Mislaneous

Comment

1: Is front tile sealed? 2: Clock needs to be replaced (owner) 3: Monitor should be moved down 6 inches



74513487\_724B\_4437\_92  
4C\_44C66DB2124C.jpeg



4315175B\_4EDA\_4322\_B  
88B\_F7796BF22269.jpeg



C968A180\_BFB0\_4AA9\_9  
D2D\_DF58CA9C4327.jpe  
g

Mislaneous

Comment

1: Pizza bags on top of soda machines should be removed (owner) - Ceiling tile replaced 2: Construction debris needs to be removed from the site 3: Wires need to be organized



4F4F2BC8\_69C3\_45D5\_9  
A8C\_2DFBB3596E3D.jpeg



BA53D6F6\_BDE7\_400E\_B  
936\_94A6A3A8A506.jpeg



18977C8D\_C836\_447C\_B  
9BA\_BBC402E4AC25.jpe  
g

Mislaneous

Comment

1: Counter not installed (owner) 2: Mop bracket is hung to low 3: Cove base is not complete



A3A59287\_AD46\_4DCD\_  
B4C3\_0A6A2046BEB8.jpe  
g



0746769B\_1060\_4568\_B  
2E7\_FAB0A050E8EA.jpeg



B43C1C78\_41B5\_4C5B\_8  
E7D\_B0407D63501F.jpeg

Mislaneous

Comment

Notes/Comments :