

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Punch List**  
**Function: Test, Adjust, & Balance**  
**Date: 12/09/2025**  
**Completed By: National TAB**

**PROJECT**  
**12-08-25 FREDDYS MIDDLETOWN, DE**

645 South Ridge Avenue

MIDDLETOWN , DE 19709

**Client**

JRI Hospitality Management  
621 Westport Blvd  
Salina, KS 67401

# National TAB

Project: 12-08-25 FREDDYS MIDDLETOWN, DE

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- RTU 1 low flow




12-08-25 FREDDYS MIDDLETOWN, DE

Project Issue Information

**Issue Name :** RTU 1 low flow  
**Description :** RTU 1 supply drop has a 4" opening and is not properly attached to discharge. Unit is losing air inside the ceiling. Unable to properly balance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :** RTU1  
**Originated Date :** 12/09/2025 - Jearod Ferrette - National TAB

Project Issue File Details



12/09/2025



12/09/2025



12/09/2025