



Diffusers 11-14 is not labeled and diffuser 11-13 may have the wrong CFM labeled. We are assuming they are both to be at 50 CFM.