

 Comfort. Under control.		1329 E Kemper Rd, Suite 4210	
		Cincinnati, OH 45246	
		will@nationaltab.com	
		P# (855)682-6822 / DIRECT# 513-889-8927	
COMPANY:	Flynn Restaurant Group	JOB NAME:	Arby's
		LOCATION:	17 Locations (see store list attached)
EMAIL:	skrekus@flynnrg.com	QUOTE #:	N/A
ATTN:	Steve Krekus	BID DATE:	3/24/2023

Thank you for allowing National TAB this opportunity to bid on the testing and balancing of this project. The following is our understanding of the scope of work and the associated cost.

TAB Scope:

Purpose of the visit is to provide a TAB of the store as well as an overview of HVAC and kitchen hood ventilation systems overall health and condition prior to remodeling. Includes the following:

- Determine equipment designs based on account standards or mechanical drawings (if provided). General standards:
 - 350-400 CFM/ton
 - Outside air ratios 20% or less
 - Slightly positive net airflow
- Evaluate equipment condition including:
 - Condenser Coil
 - Evaporator Coil
 - Belts
 - Pulleys
 - Economizers
- Measure and report the initial conditions
- Final TAB
 - RTU Supply and outside airflow (total flow only. Individual diffusers only to be balanced if affecting hood performance or causing drafting)
 - Hood Exhaust
 - Restroom Exhaust
 - Building pressure
 - Hood smoke containment test
- Light commissioning
 - Verify if units have Humidity control features
 - Verify correct humidity sensor wiring at RTU
 - Measure Entering and leaving air temperatures on evaporator coil (Outside temperature permitting. If too cold will not be able to perform temp measurements properly)
 - Program thermostats to ensure the fans remain on while the restaurant is occupied. Also verify that temperature setpoints and fan/damper operations are properly set during unoccupied hours.
 - MUA Burner operation
 - Mark outside air damper position
- Final report with any deficiencies, pictures, and asset test results.

TOTAL PRICE = \$1575 per location

Single visit only. Any parts if required will be additional. However, no parts will be provided without initial approval unless National TAB, LLC has agreed with the client for a set fee to perform specific task. Lift rental to be additional if required if not provided by owner or GC. Work to be performed 1st shift only.

Not included in price: Cleaning, Repairs, Title 24 Acceptance Testing (CA), Sheave or belt replacement, DALT, Sound and Vibration testing, Indoor Air Quality testing, or Pre-testing unless price is specified separately above.

WE HEREBY PROPOSE to furnish labor complete in accordance with NATIONAL TAB specifications, for the sum of: **\$1575.00** US Dollars per store. Payment to be made as follows:
Terms as specified by our accounting department.

<p>Acceptance of proposal - The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made in accordance to terms agreed upon.</p> <p>Client Signature: <u>Steven P Krekus</u></p> <p>Client Date of Acceptance: <u>3/28/23</u></p>	<p>Authorized Signature for NT:</p> <p><u>William Turnbough</u></p> <p>Date: <u>3/24/2023</u></p>
--	---

Interested in receiving marketing communications from National TAB? Subscribe [here](#).

Store #	Address	City
1122	10721 Lincoln Trail Hwy	Fairview Heights, IL
8424	1320 US Hwy 60 East	Republic, MO
1591	2121 Brittion Rd	Oklahoma City, OK
5881	9525 Santa Fe Dr	Overland Park, KS
1109	2148 Grand Ave	Laramie, WY
8429	1342 Southern Hill Center	West Plains, MO
7399	3740 Quebec St	Denver, CO
8344	2815 S Ten Mile Dr	Jefferson City, MO
964	2150 N Main St	Longmont, CO
5498	2221 W 6th St	Limon, CO
6377	10809 Turner Blvd	Longmont, CO
5416	300 S Lincoln	Burlington, CO
397	5130 W 92 Ave	Westminster, CO
946	1312 N Academy Blvd	Colorado Springs, CO
293	501 E 84th Ave	Thornton, CO
6980	540 Hwy 105	Monument, CO
999	3010 W. 10th St	Greeley, CO