

REMARKS

Assigned Organization: National TAB

Status: Not Submitted

Asset:

PRIORITY (HIGH/LOW/INFO ONLY)	
INFO ONLY	Manager stated that the north side of store, center back of sales, pharmacy, and south side of store have been having comfort issues. They feel there is poor airflow, temperature, and humidity issues.
LOW	RTU-2 (Sales) has a loose belt. Recommend tightening during next PM.
HIGH	RTU-7 (Customer/CBT/Acct) is vibrating on the roof and rocking in place.
INFO ONLY	RTU-9 (Pharmacy) has wires that are not landed inside the electrical compartment. May not be an issue but noting since it could not be determined where these wires go.
LOW	EF-1 (Deli Hood), EF5 (Bakery oven) and 6 (Bakery oven) belts are cracked. Recommend replacement.
HIGH	RTU-5 (Beer/Wine) is missing final filters. Recommend installing.
HIGH	RTU-7 (Customer/CBT/Acct) would not stay on even when overridden on at the BMS. Unable to measure airflow. Recommend servicing.
LOW	RTU-10 (Conference) condensate drain is incorrectly installed damaging the panel. Needs to be reinstalled/repared
LOW	Filters are dirty and need to be changed for all RTU's

Notes/Comments: