

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: PUNCHLIST
Function: Test, Adjust, & Balance
Date: 10/20/2025
Completed By: National TAB

PROJECT

Wyler Hyundai Beavercreek (Dayton, OH)

2170 Heller Drive

Dayton, OH 45434

Client

Cincinnati Air Conditioning Co.
2080 Northwest Dr
Cincinnati, OH 45231

National TAB

Project: Wyler Hyundai Beaver Creek (Dayton, OH)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- EF-1 not powered
- RTU-5 Needs Dampers
- RTUs- 1,2,3,4,5,6,7,8,9 Inoperable



Wyler Hyundai Beavercreek (Dayton, OH)

Project Issue Information

Issue Name : EF-1 not powered
Description : No power to fan, unable to balance
Created By : National TAB **Assigned To :** National TAB - Corey Dick
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/20/2025 - Aaron Cosby - National TAB




Wyler Hyundai Beavercreek (Dayton, OH)

Project Issue Information

Issue Name : RTU-5 Needs Dampers
Description : Diffusers 2,4, and 6 are without needed dampers to balance the unit
Created By : National TAB
Assigned To : National TAB - Corey Dick
Status : Open
Priority : Urgent
Asset Tag :
Originated Date : 10/20/2025 - Aaron Cosby - National TAB

Project Issue File Details





Wyler Hyundai Beavercreek (Dayton, OH)

Project Issue Information

Issue Name : RTUs- 1,2,3,4,5,6,7,8,9 Inoperable
Description : Units are powered, TSTATs are powered occupied and calling for cooling, no alarms present on SIEMENS controller. Tommy believes they're in shutdown due to smoke alarm. Fire suppression is on site today investigating 10/20. Service tech from Tom coming tomorrow 10/21

Created By : National TAB **Assigned To :** National TAB - Corey Dick
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/20/2025 - Aaron Cosby - National TAB