

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: PUNCHLIST**  
**Function: Test, Adjust, & Balance**  
**Date: 10/20/2025**  
**Completed By: National TAB**

# PROJECT

## Wyler Hyundai Beavercreek (Dayton, OH)

2170 Heller Drive

Dayton, OH 45434

### Client

Cincinnati Air Conditioning Co.  
2080 Northwest Dr  
Cincinnati, OH 45231

# National TAB

Project: Wyler Hyundai Beaver Creek (Dayton, OH)

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- RTU-1B diffuser 13 grille not installed
- RTU-7 closed OA and return damper




### Wyler Hyundai Beavercreek (Dayton, OH)

#### Project Issue Information

**Issue Name :** RTU-1B diffuser 13 grille not installed  
**Description :** The grille off diffuser 13 is not installed. Unable to balance  
**Created By :** National TAB                      **Assigned To :** National TAB - Corey Dick  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 10/22/2025 - Aaron Cosby - National TAB

#### Project Issue File Details





## Wyler Hyundai Beavercreek (Dayton, OH)

### Project Issue Information

**Issue Name :** RTU-7 closed OA and return damper  
**Description :** RTU-7 has no incoming air because the return air and outside air dampers in the unit are stuck shut. They are unresponsive to economizer controls  
**Created By :** National TAB                      **Assigned To :** National TAB - Corey Dick  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 10/22/2025 - Aaron Cosby - National TAB

#### Project Issue File Details



10/22/2025