

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: PUNCH**

**Function: Test, Adjust, & Balance**

**Date: 01/15/2026**

**Completed By: National TAB**

# **PROJECT**

**01-05-26 Whataburger #1598 - Wake Forest,  
NC**

489 Dr. Calvin Jones HWY

Wake Forest, NC 27587

## **Client**

Whataburger Restaurants

300 Concord Plaza Dr

San Antonio, TX 78216

# National TAB

Project: 01-05-26 Whataburger #1598 - Wake Forest, NC

## Table Of Contents

Section	Page #
Remarks	3

## Issue List

- EF1: Motor not functioning
- RTU1: SGRD 1,10,12



**01-05-26 Whataburger #1598 - Wake Forest, NC**

**Project Issue Information**

**Issue Name :** EF1: Motor not functioning  
**Description :** Restroom exhaust fan is powered from the roof but the motor is unresponsive.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 01/15/2026 - Cody Mauro - National TAB

Project Issue File Details



01/15/2026



**01-05-26 Whataburger #1598 - Wake Forest, NC**

**Project Issue Information**

**Issue Name :** RTU1: SGRD 1,10,12  
**Description :** Noticeably low supplying diffusers. Could be due to sharp turns from main branch, length/size of duct, change in height across distance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 01/15/2026 - Cody Mauro - National TAB

Project Issue File Details



01/15/2026



01/15/2026



01/15/2026