

# PlanGrid Task Report - Mar 2, 2026

Prepared by Dale Wheeler

Mar 1, 2026

## Description

15 tasks in this report.

## Contents

#595 [SITE 010] [NEW] CRITICAL – Final Report cannot be issued due to open Critical Tasks].....	2
#52 [REFG 506] [NEW] WIF door sweep vs threshold. ....	3
#51 [UNIT 520] [NEW] Equipment option(s) not operational.....	4
#50 [UNIT 522] [NEW] AC air filters. ....	6
#49 [UNIT 522] [NEW] AC air filters. ....	7
#48 [CNTL 499] [NEW] CRITICAL (MISC) – [TF-2 Thermostat not installed] .....	9
#47 [UNIT 499] [NEW] CRITICAL (MISC) – [Rooftop unit startups].....	10
#46 [CNTL 508] [NEW] Controls labeling. ....	12
#45 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.....	13
#44 [REFG 999] [NEW] (MISC) [Mechanical Temp. Dial] .....	14
#43 [REFG 516] [NEW] Condenser electrical disconnects. ....	16
#42 [REFG 508] [NEW] WIC/WIF panel penetrations.....	17
#39 [DUCT 501] [NEW] Insulation stick pins.....	23
#36 [UNIT 517] [NEW] Condensate piping construction. ....	24
#34 [UNIT 517] [NEW] Condensate piping construction. ....	25

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#595 [SITE 010] [NEW] CRITICAL – Final Report cannot be issued due to open Critical Tasks]**

**Status**

Open

**Start Date**

Feb 27, 2026

**Type**

Planned Work

**Created**

Mar 1, 2026 8:09 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Mar 1, 2026 8:09 PM

**Description**

Due to the CRITICAL tasks final report cannot be issued. Once all Tasks are completed and correction photos imported to PG, reach out to the TAB Supervisor to review Critical tasks.

---

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#52 [REFG 506] [NEW] WIF door sweep vs threshold.**

**Status**

Open

**Start Date**

Feb 27, 2026

**Type**

Planned Work

**Created**

Feb 27, 2026 12:28 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Mar 1, 2026 8:06 PM

**Description**

WIF door sweep is not sealed tightly with threshold when door is closed. No light should be present inspecting from the inside out with box lights off.

**Photos**



IMG\_0172

**Dale Wheeler**

Feb 27, 2026 12:29 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#51 [UNIT 520] [NEW] Equipment option(s) not operational.**

**Status**

Open

**Start Date**

Feb 27, 2026

**Type**

Planned Work

**Created**

Feb 27, 2026 11:29 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:59 AM

**Description**

AC2 power exhaust is not operational and will not turn on when placed in test mode.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0166

**Dale Wheeler**

Feb 27, 2026 11:29 AM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#50 [UNIT 522] [NEW] AC air filters.**

**Status**

Open

**Start Date**

Feb 27, 2026

**Type**

Planned Work

**Created**

Feb 27, 2026 11:29 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:31 AM

**Description**

AC2 filters are not installed  
in unit.

**Photos**



IMG\_0165

**Dale Wheeler**

Feb 27, 2026 11:29 AM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#49 [UNIT 522] [NEW] AC air filters.**

**Status**

Open

**Start Date**

Feb 27, 2026

**Type**

Planned Work

**Created**

Feb 27, 2026 11:28 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:57 AM

**Description**

Extra set of new filters for  
AC1, AC2, AC3, AC4, AC5 is  
not on site.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0167

**Dale Wheeler**

Feb 27, 2026 11:28 AM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#48 [CNTL 499] [NEW] CRITICAL (MISC) – [TF-2 Thermostat not installed]**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:18 PM  
dale@nationaltab.com

**List**

TAB Punch List


**Last Updated**

Feb 27, 2026 11:26 AM

**Description**

TF-2 seven-day programmable thermostat and rib relay are not installed. Fan is operational and was balanced to design cfm.

**Photos**



IMG\_0157

Dale Wheeler

Feb 26, 2026 12:18 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#47 [UNIT 499] [NEW] CRITICAL (MISC) – [Rooftop unit startups]**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:17 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 12:02 PM

**Description**

AC1, AC2, AC3, AC4, AC5  
unit start-ups have not been  
complete at time of TAB due  
to gas meter having not  
been set.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0160

**Dale Wheeler**

Feb 26, 2026 12:17 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#46 [CNTL 508] [NEW] Controls labeling.**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:16 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 10:41 AM

**Description**

AC3 averaging temp. sensor  
needs to be labeled.

**Photos**



IMG\_0156

**Dale Wheeler**

Feb 26, 2026 12:16 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#45 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:15 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 10:43 AM

**Description**

Caulk needs to be installed over top of spray foam and cut flush with the opening for both WIF & WIC

**Photos**



IMG\_0162

Dale Wheeler

Feb 26, 2026 12:15 PM



IMG\_0161

Dale Wheeler

Feb 26, 2026 12:15 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#44 [REFG 999] [NEW] (MISC) [Mechanical Temp. Dial]**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:14 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 10:45 AM

**Description**

WIF mechanical dial needs to be calibrated to match actual temp. inside box.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0176

**Dale Wheeler**

Feb 26, 2026 12:14 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#43 [REFG 516] [NEW] Condenser electrical disconnects.**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:14 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 10:47 AM

**Description**

WIF & WIC disconnects  
need to be labeled.

**Photos**



IMG\_0164

Dale Wheeler

Feb 26, 2026 12:14 PM



IMG\_0163

Dale Wheeler

Feb 26, 2026 12:14 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#42 [REFG 508] [NEW] WIC/WIF panel penetrations.**

**Status**

Open

**Start Date**

Feb 26, 2026

**Type**

Planned Work

**Created**

Feb 26, 2026 12:12 PM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 10:49 AM

**Description**

WIC & WIF electrical penetrations inside the boxes and on top of boxes need to be sealed.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0177

**Dale Wheeler**

Feb 26, 2026 12:13 PM



IMG\_0170

**Dale Wheeler**

Feb 26, 2026 12:13 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0174

**Dale Wheeler**

Feb 26, 2026 12:13 PM



IMG\_0179

**Dale Wheeler**

Feb 26, 2026 12:13 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0173

**Dale Wheeler**

Feb 26, 2026 12:13 PM



IMG\_0169

**Dale Wheeler**

Feb 26, 2026 12:13 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0180

**Dale Wheeler**

Feb 26, 2026 12:13 PM



IMG\_0178

**Dale Wheeler**

Feb 26, 2026 12:13 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



IMG\_0181

**Dale Wheeler**

Feb 26, 2026 12:13 PM



IMG\_0175

**Dale Wheeler**

Feb 26, 2026 12:13 PM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#39 [DUCT 501] [NEW] Insulation stick pins.**

**Status**

Open

**Start Date**

Feb 24, 2026

**Type**

Planned Work

**Created**

Feb 24, 2026 11:57 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:10 AM

**Description**

Stick Pins need to be installed on AC2 ductwork that is 24" or wider.

**Photos**



20260224\_115753\_photo

**Dale Wheeler**

Feb 24, 2026 11:57 AM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#36 [UNIT 517] [NEW] Condensate piping construction.**

**Status**

Open

**Start Date**

Feb 24, 2026

**Type**

Planned Work

**Created**

Feb 24, 2026 8:58 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:06 AM

**Description**

AC5 cleanout plug needs to be installed.

**Photos**



20260224\_085850\_photo

**Dale Wheeler**

Feb 24, 2026 8:58 AM

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954

**#34 [UNIT 517] [NEW] Condensate piping construction.**

**Status**

Open

**Start Date**

Feb 24, 2026

**Type**

Planned Work

**Created**

Feb 24, 2026 8:55 AM  
dale@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 27, 2026 11:04 AM

**Description**

AC1 & AC2 unions are not installed on each side of the p-trap.

**Photos**

**L05954\_Planters Station FSU (VA)**

3169 Godwin Boulevard, Suffolk, Virginia

L1020005954



20260224\_085622\_photo

**Dale Wheeler**

Feb 24, 2026 8:56 AM