

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246

NATIONAL

TAB

Comfort. Under control.

Report: ISSUES

Function: Test, Adjust, & Balance

Date: 10/21/2022

PROJECT

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

2517 WILSON AVE

HIGHLAND HEIGHTS, KY 41076

Client

KRNBLZ, LLC dba 5 Guys Cincinnati

247 N Westmonte Dr

Altamonte Springs, FL 32714

National TAB

Project: 10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Table Of Contents

Section	Page #
Issue Data	3



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : All rtu Filters are dirty

Description : All rtu filters are dirty

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/28/2022 - Tyler Youells - National TAB



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : All RTU OA filters

Description : RTU-1,2 Filters are missing, RTU-3 OA FILTER CLOGGED

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/28/2022 - Tyler Youells - National TAB

Project Issue File Details



FuselTfe16cf12bd48459...



FuselTd2fc6fdd60464e7...



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : Diffuser

Description : FOUR WAY DIFFUSER INSTALLED THREE WAY DIFFUSER REQUIRED

Created By : National TAB

Assigned To : National TAB - Joe Hertenstein

Status : Open

Originated Date : 10/04/2022 - Jose Chavez - National TAB



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : EF, MUA for the hood not wired.

Description : Both EFS for the hood and the MUA are not connected to high voltage. (10/28) GC States electrician will complete on Monday (10/31) Vfds do not have power

Created By : National TAB **Assigned To :** National TAB - Will Turnbough

Status : Open

Originated Date : 10/28/2022 - Tyler Youells - National TAB

Project Issue File Details



FuseITfbc715ad90b454...



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : EF-3 Missing backdraft damper
Description : Recommend getting backdraft damper installed
Created By : National TAB **Assigned To :** National TAB - Tyler Youells
Status : Open
Originated Date : 10/28/2022 - Tyler Youells - National TAB



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : hood not sealed to wall

Description : Back of hood has a gap between hood and wall

Created By : National TAB

Assigned To : National TAB - Dan Hertenstein

Status : Open

Originated Date : 10/04/2022 - Zack Epps - National TAB

Project Issue File Details



Hood2.jpeg



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : RTU CLEANING

Description : RECOMMEND RTU CLEANING

Created By : National TAB

Assigned To : National TAB - Joe Hertenstein

Status : Open

Originated Date : 10/04/2022 - Jose Chavez - National TAB

Project Issue File Details



File.jpeg



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : RTU-1,2

Description : Gas piping to rtu1,2 valves are off

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/28/2022 - Tyler Youells - National TAB

Project Issue File Details



FuselTe13be88aaf8744e...



FuselT3360b7c3238a425...



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : RTU-1,3 condensate drains
Description : Condensate drains are not correct/ have fallen apart
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Originated Date : 10/28/2022 - Tyler Youells - National TAB



Comfort. Under control.

10-24 FIVE GUYS - HIGHLAND HEIGHTS, KY (NEW STORE)

Project Issue Information

Issue Name : RTU-3 Blower is extremely dirty

Description : Rtu-3 blower wheel has a lot of dirt buildup. The unit filters are also dirty. The units is at the lower end of design, cleaning the blower and replacing filters will likely bring it to design cfm

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/28/2022 - Tyler Youells - National TAB

Project Issue File Details



FuselT64ff27d3f893448...