

**Report By:**

National TAB  
105 Stone Village Drive  
Fort Mill, SC 29708



**Report: Deficiency Report**  
**Function: Test, Adjust, & Balance**  
**Date: 02/18/2026**  
**Completed By: National TAB**

**PROJECT**  
**02-16-26 QT #1074 MONROE, NC**

603 W ROOSEVELT BLVD

MONROE, NC

**Client**

QUIKTRIP  
4705 SOUTH 129TH EAST AVENUE  
TULSA, OK 74134

## Issue List

- EF-2 speed controller doesn't work
- RTU 3 economizer not working




**02-16-26 QT #1074 MONROE, NC**

**Project Issue Information**

**Issue Name :** EF-2 speed controller doesn't work  
**Description :** The speed controller on EF-2 does not work. The combi oven grille is under design, and the men's restroom cannot spare enough air to bring it to design. The fan must be sped up.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** EF2  
**Originated Date :** 02/18/2026 - Christian Moller - National TAB

Project Issue File Details



02/18/2026



02/18/2026



02-16-26 QT #1074 MONROE, NC

**Project Issue Information**

**Issue Name :** RTU 3 economizer not working  
**Description :** The economizer on RTU 3 does not respond to the Emerson board setpoints. For balancing purposes, the OA was set and left at the high speed position so is bringing in extra when the hood is off. Position was physically marked in the unit.  
**Created By :** National TAB      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Urgent      **Asset Tag :** RT-3  
**Originated Date :** 02/18/2026 - Christian Moller - National TAB


Project Issue File Details



02/18/2026



02/18/2026



02/18/2026