



Comfort. Under control.

05-16 MATTISON AVE - HOUSTON, TX (CHAMPION FOREST)

Project Issue Information

Issue Name : EF5 dampers are not accessible

Description : Dampers located at the main trunk, main trunk is installed in the middle of the hard ceiling and above the supply ductwork. Mechanical contractor has been informed and will be coming out to investigate.

Created By : National TAB

Assigned To : National TAB - Travis Halter

Status : Open

Originated Date : 05/18/2022 - Travis Halter - National TAB