



Comfort. Under control.

Nestle (Mt Sterling, KY)

Project RFI Information

Issue Name :	SF 2-98 Sauce room	Organization :	SF 2-98 Sauce room
Status :	Pending	Assigned To :	National TAB - JOE HERTENSTEIN
Shared To :		Created :	Tyler Youells
Open :	05/11/2021 - Tyler Youells - National TAB	Description:	Unit not running. disconnect is on. One belt is missing. Is there a sequence of operation?

Project RFI File Details

1. [Open](#) File.jpg

Project RFI Response Details

- **05/27/2021** **National TAB - JOE HERTENSTEIN**
 - FACILITIES TEAM TO REVIEW FOR MAINTENANCE-ELECTRICAL ISSUES & NEEDS NEW BELT

- **05/20/2021** **National TAB - Tyler Youells**
 - Short in electric box.
 - 1. [Open](#) File.jpg

- **05/20/2021** **National TAB - Tyler Youells**
 - Control panel located in mezz. Near sf drop and next to condensate pipe. Fan does not turn on when switch is on in the mezz. There looks to be a short in the electric panel see pic
 - 1. [Open](#) File.jpg

- **05/19/2021** **National TAB - Alec Lewis**
 - Two supply and two exhaust fans serve sauce room. This is manually turned off in mezzanine when needed for temperatures.