



Nestle (Mt Sterling, KY)

Project RFI Information

Issue Name :	SF 9-96 L6 OVEN	Organization :	SF 9-96 L6 OVEN
Status :	Pending	Assigned To :	National TAB - JOE HERTENSTEIN
Shared To :		Created :	Tyler Youells
Open :	05/11/2021 - Tyler Youells - National TAB	Description:	Fan is not running. Disconnect is off and locked out. Motor and fan spin freely. One belt is missing. Damper partially open 0.25"

Project RFI File Details

1. [Open](#) File.jpg
2. [Open](#) File(1).jpg

Project RFI Response Details

- **05/27/2021 National TAB - JOE HERTENSTEIN**
 - FACILITIES TEAM TO REVIEW FOR MAINTENANCE-RECOMMEND EXHAUST FAN NEXT TO SUPPLY FAN TO HAVE DISCHARGE OF FAN RAISED & CHANGED DIRECTION SO SF 9-96 DOES NOT BRING IN THE EXHAUST WHEN ON.
- **05/19/2021 National TAB - Alec Lewis**
 - Reason it is locked out, it sucks in the oven exhaust stack next to it and combustion smell enters the space.
- **05/19/2021 National TAB - Alec Lewis**
 - Fan abandoned and recommend removing. Locked out.