



## Nestle (Mt Sterling, KY)

### Project RFI Information

**Issue Name :** SF 9-96 L6 OVEN    **Organization :** SF 9-96 L6 OVEN  
**Status :** Pending    **Assigned To :** National TAB - JOE HERTENSTEIN  
**Shared To :**    **Created :** Tyler Youells  
**Open :** 05/11/2021 - Tyler Youells - National TAB    **Description:** Fan is not running. Disconnect is off and locked out. Motor and fan spin freely. One belt is missing. Damper partially open 0.25"

#### Project RFI File Details

- 1. [Open](#) File.jpg
- 2. [Open](#) File(1).jpg

#### Project RFI Response Details

- **05/27/2021**    **National TAB - JOE HERTENSTEIN**
  - FACILITIES TEAM TO REVIEW FOR MAINTENANCE-RECOMMEND EXHAUST FAN NEXT TO SUPPLY FAN TO HAVE DISCHARGE OF FAN RAISED & CHANGED DIRECTION SO SF 9-96 DOES NOT BRING IN THE EXHAUST WHEN ON.
- **05/19/2021**    **National TAB - Alec Lewis**
  - Reason it is locked out, it sucks in the oven exhaust stack next to it and combustion smell enters the space.
- **05/19/2021**    **National TAB - Alec Lewis**
  - Fan abandoned and recommend removing. Locked out.