



02-10-25 FREDDY'S - DERBY, KS (DERBY) - RENEW


**Project Issue Information**

**Issue Name :** Dining room middle unit temp sensor  
**Description :** Middle thermostat is reading over 90 degrees but I measured 78 degrees in the dining room. Temp sensor is most likely bad  
**Created By :** National TAB **Assigned To :** National TAB - Kyle Henry  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 02/18/2025 - Kyle Henry - National TAB

Project Issue File Details



02/18/2025



02/18/2025