

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 12/11/2024
Completed By: National TAB

PROJECT

12-09-2024 FREDDY'S - HUNTSVILLE, AL

7001 Cabela Drive

Huntsville, AL 35806

Client

HLI FOODS

National TAB

Project: 12-09-2024 FREDDY'S - HUNTSVILLE, AL

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- EF-1
- EF-2
- KEF-1 Grease Pan
- KEF-2 Bolts
- KEF-2 Grease Pan
- RTU-1 Final Filter



12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : EF-1
Description : EF-1 is not wired to power. Unable to balance unit until this is resolved.
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details





12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : EF-2
Description : EF-2 is not wired to power. Unable to balance unit until this is resolved.
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/12/2024



12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : KEF-1 Grease Pan
Description : Grease pan was not installed on KEF-1. Recommend having mechanical install.
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/12/2024



12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : KEF-2 Bolts
Description : KEF-3 is currently not bolted to the curb.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/12/2024



12/12/2024



12/12/2024



12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : KEF-2 Grease Pan
Description : Grease pan was not installed on KEF-2. Recommend having mechanical install.
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/12/2024



12-09-2024 FREDDY'S - HUNTSVILLE, AL

Project Issue Information

Issue Name : RTU-1 Final Filter
Description : Factory final filters are currently installed in RTU-1. Recommend installed MERV 8 or better filters in unit. 4 count 20"X20"X2"
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : High **Asset Tag :**
Originated Date : 12/12/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/12/2024