




06-17-24 CAVA YUKON, OK (10TH ST)


Project Issue Information

Issue Name : EF2 - AIRFLOW
Description : FAN IS ON HIGH AIRFLOW, NO FAN SPEED CONTROLLER INSTALLED. RECOMMEND INSTALLED SPEED CONTROLLER TO BRING FAN INTO DESIGN.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 06/19/2024 - Kristopher Passley - National TAB

Project Issue File Details



IMG_1234.jpeg



IMG_1194.jpeg