




Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : EF1-4 Grease Cup
Description : Grease cups are not installed for hood exhaust fans.
Created By : National TAB **Assigned To :** National TAB - Travis Halter
Status : Open
Originated Date : 09/26/2022 - Travis Halter - National TAB

Project Issue File Details



FuseIT3d737ebc6d0840....



FuseIT55a8780abc9344....



Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : HD1&2 Control Valve

Description : Valve is not installed

Created By : National TAB

Assigned To : National TAB - Travis Halter

Status : Open

Originated Date : 09/26/2022 - Travis Halter - National TAB

Project Issue File Details



FuselT9f13b906869f45....

Project Issue Response Details

- **09/27/2022 National TAB - Travis Halter**
 - Gas lines are still being connected, unable to turn on kitchen equipment for final smoke test.