

# PlanGrid Task Report - Nov 13, 2024

Prepared by Ian Fuller

Nov 13, 2024

## Description

3 tasks in this report.

## Contents

#8 [CNTL 509] [NEW] Ansul pull labeling.....	2
#7 [CURT 501] [NEW] Air curtain power. ....	3
#3 [UNIT 514] [NEW] Equipment gas piping. ....	4

#8 [CNTL 509] [NEW] Ansul pull labeling.

<b>Status</b>	<b>Start Date</b>
Open	Nov 11, 2024
<b>Type</b>	<b>Created</b>
Planned Work	Nov 12, 2024 9:45 AM ianf@nationaltab.com
<b>Description</b>	<b>Last Updated</b>
Label all ansul pull stations for which hoods they serve.	Nov 12, 2024 9:54 AM

Photos



IMG\_8890

Ian Fuller

Nov 12, 2024 9:54 AM

#7 [CURT 501] [NEW] Air curtain power.

<b>Status</b>	<b>Start Date</b>
Open	Nov 11, 2024
<b>Type</b>	<b>Created</b>
Planned Work	Nov 12, 2024 9:45 AM ianf@nationaltab.com
<b>Description</b>	<b>Last Updated</b>
Air curtain #2 power does not cycle properly from local disconnect at time of TAB inspection.	Nov 12, 2024 9:54 AM

Photos



IMG\_8898

Ian Fuller

Nov 12, 2024 9:54 AM

### #3 [UNIT 514] [NEW] Equipment gas piping.

<b>Status</b>	<b>Start Date</b>
Open	Nov 11, 2024
<b>Type</b>	<b>Created</b>
Planned Work	Nov 12, 2024 9:45 AM ianf@nationaltab.com
<b>Description</b>	<b>Last Updated</b>
Equipment gas startups incomplete per normal CFA specifications. Gas valve need to be turned on to unit.	Nov 12, 2024 9:53 AM

#### Photos



IMG\_8901

Ian Fuller

Nov 12, 2024 9:52 AM