

PlanGrid Task Report - Jun 6, 2025

Prepared by Stephen Tassinaro

Jun 6, 2025

Description

3 tasks in this report.

Contents

#238 [CNTL 511] [NEW] Ansul system controls.	2
#230 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.....	4
#229 [REFG 516] [NEW] Condenser electrical disconnects.	7

#238 [CNTL 511] [NEW] Ansul system controls.

Status

Open

Start Date

Mar 15, 2025

Type

Planned Work

Created

Mar 21, 2025 10:35 AM
bens@nationaltab.com

Description

Ansul wiring incomplete at cans or panel interlock still jumped out at time of TAB inspection.

Last Updated

Jun 6, 2025 10:44 AM

Comments

Fire relay is still bypassed.

Stephen Tassinaro Jun 6, 2025

Photos

L05457_Treetops FSU (MS)

2520 Lakeland Drive, Flowood, Mississippi

L1020005457



IMG_6325

Stephen Tassinaro

Jun 6, 2025 10:44 AM



20250324_063534_photo

Zack Robb

Mar 24, 2025 7:35 AM

#230 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.

Status

Open

Start Date

Mar 15, 2025

Type

Planned Work

Created

Mar 21, 2025 10:35 AM
bens@nationaltab.com

Description

PVC pipe chase risers are not sealed with spray foam and silicone to prevent weather/pest infiltration. The spray foam should be cut flush to the piping with a layer of silicone over the top.

Last Updated

Jun 6, 2025 10:51 AM

Comments

The risers still need silicone over the foam

Ben Searles Apr 30, 2025

No silicone nor is the foam cut flush.

Stephen Tassinaro Jun 6, 2025

Photos



IMG_6316
Stephen Tassinaro
Jun 6, 2025 10:51 AM



IMG_6317
Stephen Tassinaro
Jun 6, 2025 10:51 AM

L05457_Treetops FSU (MS)
2520 Lakeland Drive, Flowood, Mississippi
L1020005457



20250331_143510_photo
Zack Robb
Mar 31, 2025 3:35 PM



IMG_0467
Ben Searles
Mar 21, 2025 10:42 AM

#229 [REFG 516] [NEW] Condenser electrical disconnects.

Status

Open

Start Date

Mar 15, 2025

Type

Planned Work

Created

Mar 21, 2025 10:35 AM
bens@nationaltab.com

Description

Electrical disconnects are not properly labeled to indicate which equipment they serve.

Last Updated

Jun 6, 2025 10:51 AM

Comments

Disconnects themselves are not labeled.

Stephen Tassinaro Jun 6, 2025

Photos



IMG_6318
Stephen Tassinaro
Jun 6, 2025 10:51 AM



IMG_6319
Stephen Tassinaro
Jun 6, 2025 10:51 AM

L05457_Treetops FSU (MS)
2520 Lakeland Drive, Flowood, Mississippi
L1020005457



20250331_143355_photo
Zack Robb
Mar 31, 2025 3:33 PM



20250331_143335_photo
Zack Robb
Mar 31, 2025 3:33 PM

L05457_Treetops FSU (MS)

2520 Lakeland Drive, Flowood, Mississippi

L1020005457



IMG_0491

Ben Searles

Mar 21, 2025 10:42 AM