

TAB Punch List for CFA 1143

Prepared by Ben Searles

Jan 23, 2025

Description

5 tasks in this report.

Contents

| | |
|--|---|
| #264 [EXHA 999] [EXIST] Restroom diffuser is dirty..... | 2 |
| #263 [HOOD 512] [NEW] Grease cup and fry chute..... | 3 |
| #262 [HOOD 999] [EXIST] Capture jet intake is dirty..... | 4 |
| #261 [UNIT 512] [EXIST] Equipment hail guards..... | 5 |
| #260 [UNIT 522] [EXIST] AC air filters. | 6 |

#264 [EXHA 999] [EXIST] Restroom diffuser is dirty

Status

Open

Start Date

Jan 18, 2025

Type

Planned Work

Created

Jan 23, 2025 6:53 PM
bens@nationaltab.com

Description

Women's restroom diffuser is
dirty and recommended to
be cleaned

Last Updated

Jan 23, 2025 6:54 PM

#263 [HOOD 512] [NEW] Grease cup and fry chute.

Status

Open

Start Date

Jan 18, 2025

Type

Planned Work

Created

Jan 23, 2025 6:53 PM
bens@nationaltab.com

Description

Hood 3 is missing its grease cup.

Last Updated

Jan 23, 2025 6:58 PM

Photos



IMG_0027

Ben Searles

Jan 23, 2025 6:58 PM

#262 [HOOD 999] [EXIST] Capture jet intake is dirty

Status

Open

Start Date

Jan 18, 2025

Type

Planned Work

Created

Jan 23, 2025 6:53 PM
bens@nationaltab.com

Description

Capture jet intake is dirty and recommended to be cleaned.

Last Updated

Jan 23, 2025 6:58 PM

Photos



IMG_0028

Ben Searles

Jan 23, 2025 6:58 PM

#261 [UNIT 512] [EXIST] Equipment hail guards.

Status

Open

Start Date

Jan 18, 2025

Type

Planned Work

Created

Jan 23, 2025 6:53 PM
bens@nationaltab.com

Description

Equipment hail guards are missing or installed incorrectly. No severe damage can be seen.

Last Updated

Jan 23, 2025 6:59 PM

Photos



IMG_0025

Ben Searles

Jan 23, 2025 6:59 PM

#260 [UNIT 522] [EXIST] AC air filters.

Status

Open

Start Date

Jan 18, 2025

Type

Planned Work

Created

Jan 23, 2025 6:53 PM
bens@nationaltab.com

Description

Filters are dirty and recommended to be replaced.

Last Updated

Jan 23, 2025 6:53 PM
