

# PlanGrid Task Report - Mar 11, 2025

Prepared by Will T

Mar 11, 2025

## Description

5 tasks in this report.

## Contents

#128 [HOOD 508] [NEW] Sidejet arm angle bracket. ....	2
#124 [UNIT 517] [NEW] Condensate piping construction. ....	5
#123 [DUCT 501] [NEW] Insulation stick pins. ....	8
#122 [REFG 505] [NEW] WIC door sweep vs threshold. ....	10
#121 [REFG 506] [NEW] WIF door sweep vs threshold. ....	15

# #128 [HOOD 508] [NEW] Sidejet arm angle bracket.

**Status**

Open

**Start Date**

Nov 4, 2024

**Sheet**

MH-1.1

**Type**

Planned Work

**Created**


Nov 4, 2024 5:07 PM  
gabem@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 21, 2025 1:54 PM



**Description**

The Halton supplied angle bracket that connects the integral sidejet arm to the counter is missing or not installed correctly. Secure bracket to arm and bracket to counter underneath removeable fry dump via stainless steel rivets.

**Comments**

No documentation provided

Will T Nov 22, 2024

Brackets have been installed correctly. Ready for inspection.

Tim Hostetler Jan 13, 2025

The bracket can not be riveted. if it is not removable the fryer will not be able to be pulled out. Also, this would void warranty.

Tim Hostetler Feb 11, 2025

Re-opened for lack of documentation. See plans, bracket connects sidearm capture jet to counter, not to fryer.

Will T Feb 21, 2025

**Photos**



0863F7E0-4D20-46F4-A9F6-D2D1F382957D

**Tim Hostetler**

Feb 9, 2025 9:47 AM



3243FCE7-C157-44A7-A92B-6C6905AE4BB6

**Tim Hostetler**

Feb 9, 2025 9:44 AM



IMG\_1663

**Gabe Merk**

Nov 4, 2024 6:38 PM



L05290\_Maumee FSU (OH)

603 Pointe Blvd., Maumee, OH

L1020005290



image

**Joe Spagnoli**

Nov 21, 2024 9:05 AM



image

**Joe Spagnoli**

Nov 21, 2024 9:05 AM



image

**Joe Spagnoli**

Nov 21, 2024 9:04 AM



image

**Joe Spagnoli**

Nov 21, 2024 9:04 AM



image

**Joe Spagnoli**

Nov 13, 2024 3:59 PM



IMG\_1623

**Gabe Merk**

Nov 4, 2024 6:39 PM

# #123 [DUCT 501] [NEW] Insulation stick pins.

Status  
Open

Start Date  
Nov 4, 2024

Sheet  
M-001

Type  
Planned Work

Created  
Nov 4, 2024 5:07 PM  
gabem@nationaltab.com

List  
TAB Punch List

Last Updated  
Feb 21, 2025 1:48 PM

## Description

External insulation on bottom of ducts 24" or wider is to be supported by stick pins 18" on center. Cut pins and apply tape or mastic over stick pin washers.

## Comments


Per direction by national tab missing mastic over pins

Adam Friedrich Nov 15, 2024

Re-opened for insufficient documentation. Cannot clearly see stick pins installed, insulation is bunched and sagging.

Will T Feb 21, 2025

## Photos





image

**Joe Spagnoli**

Nov 12, 2024 1:02 PM



image

**Joe Spagnoli**

Nov 12, 2024 12:57 PM



image

**Joe Spagnoli**

Nov 12, 2024 12:49 PM



IMG\_1650

**Gabe Merk**

Nov 4, 2024 6:39 PM

## #122 [REFG 505] [NEW] WIC door sweep vs threshold.

**Status**

Open

**Start Date**

Nov 4, 2024

**Type**

Planned Work

**Created**

Nov 4, 2024 5:07 PM  
gabem@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 21, 2025 1:46 PM

**Description**

WIC door sweep is not sealed tightly with threshold when door is closed. Only translucent light should be present inspecting from the inside out with box lights off.

**Comments**

What work was performed here to make the correction please document

Adam Friedrich Nov 18, 2024

Refrigeration company adjusted the threshold and seal. Ready for inspection.

Tim Hostetler Jan 13, 2025

Re-opened for lack of documentation, need a photo from the inside with the light off.

Will T Feb 21, 2025

**Photos**



IMG\_3119

Joe Spagnoli

Nov 19, 2024 12:21 PM



IMG\_3118

Joe Spagnoli

Nov 19, 2024 12:20 PM



IMG\_3116  
**Joe Spagnoli**  
Nov 19, 2024 12:16 PM



IMG\_3114  
**Joe Spagnoli**  
Nov 19, 2024 11:43 AM



IMG\_3114  
**Joe Spagnoli**  
Nov 19, 2024 11:43 AM



image  
**Joe Spagnoli**  
Nov 18, 2024 10:46 AM



photo nov 12 2024, 10 25 51 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



photo nov 12 2024, 10 25 51 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



photo nov 12 2024, 10 25 44 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



photo nov 12 2024, 10 25 44 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



IMG\_1653

**Gabe Merk**

Nov 4, 2024 6:39 PM

## #121 [REFG 506] [NEW] WIF door sweep vs threshold.

**Status**

Open

**Start Date**

Nov 4, 2024

**Type**

Planned Work

**Created**

Nov 4, 2024 5:07 PM  
gabem@nationaltab.com

**List**

TAB Punch List

**Last Updated**

Feb 21, 2025 1:45 PM

**Description**

WIF door sweep is not sealed tightly with threshold when door is closed. No light should be present inspecting from the inside out with box lights off.

**Comments**

What work was performed to correct this?

Adam Friedrich Nov 18, 2024

Refrigeration company adjusted the threshold and seal. Ready for inspection.

Tim Hostetler Jan 13, 2025

Re-opened for insufficient documentation. Need a photo from inside with the light off.

Will T Feb 21, 2025

**Photos**



image

**Joe Spagnoli**

Nov 18, 2024 10:47 AM



photo nov 12 2024, 10 25 51 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



photo nov 12 2024, 10 25 44 am

**Joe Spagnoli**

Nov 12, 2024 10:25 AM



IMG\_1654

**Gabe Merk**

Nov 4, 2024 6:40 PM