

Report By:

National TAB
105 Stone Village Drive
Fort Mill, SC 29708



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 10/10/2025
Completed By: National TAB

PROJECT
10-06-25 QT #1109 ANDERSON, SC

2901 N MAIN ST

ANDERSON, SC

Client

QUIKTRIP
4705 SOUTH 129TH EAST AVENUE
TULSA, OK 74134

Issue List

- NEITHER EF WORKING
- RTU 3 WRONG COOK LINE DIFFUSERS



10-06-25 QT #1109 ANDERSON, SC

Project Issue Information

Issue Name : NEITHER EF WORKING
Description : Neither of the exhaust fans are running. Balancing could not take place, both units have power.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/10/2025 - Christian Moller - National TAB

Project Issue File Details



10/10/2025



10/10/2025



10-06-25 QT #1109 ANDERSON, SC

Project Issue Information

Issue Name : RTU 3 WRONG COOK LINE DIFFUSERS
Description : The diffusers for RTU 3 in front of the hood are wrong. Plans call for 4 double deflection grilles.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :** RT-3
Originated Date : 10/10/2025 - Christian Moller - National TAB

Project Issue File Details

