

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: TAB Report
Function: Test, Adjust, & Balance
Date: 11/21/2025
Completed By: National TAB

PROJECT

**11-17-25 WHATABURGER #1629 HOUSTON,
TX**

3929 Southwest Fwy

Houston, TX

Client

Whataburger Restaurants
300 Concord Plaza Dr

San Antonio, TX 78216

National TAB

Project: 11-17-25 WHATABURGER #1629 HOUSTON, TX

Table Of Contents

Section	Page #
Issue List	3

Issue List

- KEF2 UNABLE TO LIFT BACK



11-17-25 WHATABURGER #1629 HOUSTON, TX

Project Issue Information

Issue Name : KEF2 UNABLE TO LIFT BACK
Description : KITCHEN EXHAUST FAN 2 WAS NOT ABLE TO LIFT BACK FULLY. IT COULD LIFT ENOUGH TO TAKE PRESSURE READINGS, BUT THIS WILL NEED TO BE FIXED SO THE DUCT CAN BE CLEANED IN THE FUTURE.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :** KEF2
Originated Date : 11/21/2025 - Zack Osborne - National TAB

Project Issue File Details



11/21/2025