



Comfort. Under control.

02-13-23 FAMILY DOLLAR - BROADHEAD, WI

Project Issue Information

Issue Name : RTU-2 Motor Sheave Frozen.

Description : RTU-2 motor sheave was found spun in on itself to 0 turns open. A key and set screw were not found installed, and the pulley could not be loosened free. Recommend pulley is serviced and sheave is set to 1 turn open.


Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 02/14/2023 - Michael McDonnell - National TAB

Project Issue File Details



SheaveFrozen.jpeg



Comfort. Under control.

02-13-23 FAMILY DOLLAR - BROADHEAD, WI

Project Issue Information

Issue Name : RTU-3 Motor Sheave Stuck.

Description : Set key is stuck in the motor sheave and could not be loosened to adjust sheave. Recommend pulley is serviced and sheave is set to 1 turn open.

Created By : National TAB

Assigned To : National TAB - Michael McDonnell

Status : Open

Originated Date : 02/14/2023 - Michael McDonnell - National TAB

Project Issue File Details



Sheave.jpeg