

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Punchlist**  
**Function: Test, Adjust, & Balance**  
**Date: 03/31/2025**  
**Completed By: National TAB**

**PROJECT**  
**03-31-25 WAWA #7409 CHESTERFIELD, IN**

2501 POWELL AVENUE

NASHVILLE, TN 37204

**Client**

Wawa  
260 West Baltimore Pike

Wawa, PA 19063

# National TAB

Project: 03-31-25 WAWA #7409 CHESTERFIELD, IN

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- EF-3 Above Design
- RTU-1 Diffuser 6
- RTU-3 Powered Exhaust



**03-31-25 WAWA #7409 CHESTERFIELD, IN**

**Project Issue Information**

**Issue Name :** EF-3 Above Design  
**Description :** EF-3 is above design flow and is not equipped with a speed controller.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 03/31/2025 - Jordan Best - National TAB



**03-31-25 WAWA #7409 CHESTERFIELD, IN**

**Project Issue Information**

**Issue Name :** RTU-1 Diffuser 6  
**Description :** RTU-1, diffuser 6 is above design. Damper handle was stuck and was broken when I tried to free it. MC will be on site 04/01/25 to replace.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 03/31/2025 - Jordan Best - National TAB



**03-31-25 WAWA #7409 CHESTERFIELD, IN**

**Project Issue Information**

**Issue Name :** RTU-3 Powered Exhaust  
**Description :** Powered exhaust for RTU-3 is constantly running while OA damper for unit is closed.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 03/31/2025 - Jordan Best - National TAB