

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 05/19/2025
Completed By: National TAB

PROJECT

05-19-25 WAWA #8196 POTTSTOWN, PA

157 EVERGREEN RD

LOWER POTTS GROVE TOWNSHIP, PA 19464

Client

Wawa
260 West Baltimore Pike
Wawa, PA 19063

Issue List

- EF1-1 - Missing Damper




05-19-25 WAWA #8196 POTTSTOWN, PA

Project Issue Information

Issue Name : EF1-1 - Missing Damper
Description : Damper is missing or could not be located for exhaust diffuser 1-1 (staging room). Diffuser is currently at 131 CFM (131% design) and cannot be adjusted to design. Recommend installing.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : High **Asset Tag :**
Originated Date : 05/19/2025 - Mark Johnson - National TAB

Project Issue File Details



05/19/2025



05/19/2025