

STORE FRONT

RTU-1



RTU-2

RTU-3



RTU-4

RTU-5



RTU-6

RTU-7



RTU-8



RTU-9



RTU-10



RTU-11



RTU-12



RTU-13



RTU-14



RTU-15



RTU-16

RTU-17



RTU-18

RTU-19



RTU-20

RTU-21



RTU-22

EF-ER



EF-CC



EF-R1



EF-H5



EF-S



EF-H4



EF-G1&G2



EF-H1, H2, H3



EF-R4



EF-R2, P, ER



EF-R3



HOODS-R1&L1



HOOD-2



HOOD-3

HOOD-4



HOOD-5





PERIMETER UNIT RETURN
GRILLES DIRTY.



SALES FLOOR UNIT RETURN
GRILLES DIRTY.



NEARLY ALL CONDENSATE P TRAPS DISCONNECTED FROM ROOFTOP DRAINS.



SAGS PRESENT IN ROOFTOP CONDENSATE DRAINS.



RTU-2 AND 15 HAVE MODERATELY DIRTY EVAPORATOR COILS.



RTU-6, 10, 12, 15, 22 HAVE DIRTY CONDENSER COILS.



RTU-5, 7 HAVE BAD VFDs. POWER CONNECTED DIRECTLY TO MOTOR FOR TESTING BY FACILITY MANAGEMENT.



REFRIGERATION SYSTEM ICING. FACILITY MANAGEMENT NOTIFIED.



EF-H3 MOTOR PULLEY EDGES WORN.



EF-S OUT OF COMMISSION. NO POWER RUN TO UNIT. WASP NESTS BUILT ALONG FAN WHEEL.



EF-R4 BIRD SCREEN DIRTY.