



Project Summary

The scope of this project is to perform a survey of the existing RTU's, EF's, MUA, and hoods. This includes measuring as-is airflows, inspecting the equipment for maintenance issues, and providing additional insight as to the performance and condition.

The major issues that were identified are noted on the following pages. These provide a snapshot of the major findings. Following that are checklists, pictures, and asset pages that have additional details and technical information regarding the equipment. If there are any questions about the results please reach out to our team for clarification.