

L05163_Gibsonton & 301 FSU (FL)

10110 U.S. 301, Riverview, Florida

L1020005163

PlanGrid Task Report - Jul 25, 2024

Prepared by Ian Fuller

Jul 25, 2024

Description

1 task in this report.

#1 [REFG 199] (MISC) Condensor is making excessive noise and shaking

Status

Open

Start Date

Jul 22, 2024

Type

Planned Work

Created

Jul 22, 2024 5:27 PM
ianf@nationaltab.com

Description

Condensor#3 on roof is shaking and making loud noises. Condensor turned off at the disconnect to prevent further damage.

Last Updated

Jul 22, 2024 5:30 PM

Photos



IMG_7866

Ian Fuller

Jul 22, 2024 5:30 PM