

TAB PUNCHLIST

Prepared by David Annan

Jan 28, 2025

Description

7 tasks in this report.

Contents

#12 ANSUL Pull stations are not labled	2
#11 AC-1: Heating component was not functional.....	4
#10 High Voltage cover is not installed	6
#9 Gusset bolts for Hood 2 are not installed	8
#8 Annunciators are not labeled.....	9
#7 Sensors are not labeled	11
#5 Hood-1 capture jets are not powered	13

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325

#12 ANSUL Pull stations are not labled

Status

Open

Type

Issue

List

Punch List

Description

All ANSUL pull stations are not labeled. See page M-201 for acceptable spec.

Assignees

fbecker@conboy-mannion.com

Watchers

jdevlin@conboy-mannion.com
fbecker@conboy-mannion.com

Start Date

Jan 22, 2025

Due At

Jan 25, 2025

Created


Jan 28, 2025 10:39 AM
david@nationaltab.com

Last Updated

Jan 28, 2025 10:41 AM

Sheet

M-201



Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7001

David Annan

Jan 28, 2025 10:41 AM

#11 AC-1: Heating component was not functional

Status

Open

Assignees

fbecker@conboy-mannion.com

Type

Issue

Watchers

fbecker@conboy-mannion.com
jdevlin@conboy-mannion.com

Description

AC-1 heating was not functional. Recommend that unit is serviced.

Start Date

Jan 22, 2025

Due At

Jan 25, 2025

Created

Jan 28, 2025 10:36 AM
davida@nationaltab.com

Last Updated

Jan 28, 2025 10:39 AM

Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7058

David Annan

Jan 28, 2025 10:38 AM

#10 High Voltage cover is not installed

Status

Open

Assignees

fbecker@conboy-mannion.com

Type

Issue

Watchers

fbecker@conboy-mannion.com
jdevlin@conboy-mannion.com

List

Punch List

Description

The high voltage cover for the T-500 Suncoast panel is not installed.

Start Date

Jan 21, 2025

Due At

Jan 25, 2025

Created

Jan 28, 2025 10:33 AM
davida@nationaltab.com

Last Updated

Jan 28, 2025 10:36 AM

Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7060

David Annan

Jan 28, 2025 10:36 AM

#9 Gusset bolts for Hood 2 are not installed

Status

Open

Assignees

fbecker@conboy-mannion.com

Type

Issue

Watchers

fbecker@conboy-mannion.com
jdevlin@conboy-mannion.com

List

Punch List

Description

The gusset bolts for Hood-2 are not installed.

Start Date

Jan 21, 2025

Due At

Jan 24, 2025

Created

Jan 22, 2025 12:37 PM
davida@nationaltab.com

Last Updated

Jan 22, 2025 12:39 PM

Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7021

David Annan

Jan 22, 2025 12:38 PM



IMG_7022

David Annan

Jan 22, 2025 12:38 PM

#8 Annunciators are not labeled

Status

Open

Type

Issue

List

Punch List

Description

Annunciators are not labeled. See page M-701 for spec.

Assignees

fbecker@conboymannion.com

jdevlin@conboymannion.com

jdevlin@conboymannion.com

jdevlin@conboymannion.com

Watchers

fbecker@conboymannion.com

jdevlin@conboymannion.com


jdevlin@conboymannion.com

jdevlin@conboymannion.com

Start Date

Sheet

M-701



L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325

Jan 21, 2025

Due At

Jan 24, 2025

Created

Jan 22, 2025 12:34 PM

davida@nationaltab.com

Last Updated

Jan 22, 2025 12:36 PM

#7 Sensors are not labeled

Status

Open

Type

Issue

List

Punch List

Description

Temp and humidity sensors are not labeled. Refer to page M-701 note #4 for exact specifications.

Assignees

fbecker@conboy-mannion.com

Watchers

fbecker@conboy-mannion.com
jdevlin@conboy-mannion.com

Start Date

Jan 21, 2025

Due At

Jan 24, 2025

Created


Jan 22, 2025 12:31 PM
david@nationaltab.com

Last Updated

Jan 22, 2025 12:34 PM

Sheet

M-701



Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7025

David Annan

Jan 22, 2025 12:34 PM

#5 Hood-1 capture jets are not powered

Status

Open

Assignees

fbecker@conboy-mannion.com

Type

Issue

Watchers

jdevlin@conboy-mannion.com
fbecker@conboy-mannion.com

Location

Kitchen

List

Punch List

Start Date

Jan 21, 2025

Root Cause

Quality >
Incomplete work

Due At

Jan 24, 2025

Description

Hood 1 capture jets were not powered. Unable to balance to design.

Created

Jan 22, 2025 12:09 PM
david@nationaltab.com

Last Updated

Jan 28, 2025 10:48 AM

Photos

L05325_Central Avenue & Colvin Avenue (NY)...

944 Central Avenue, Albany, New York

L01020005325



IMG_7029

David Annan

Jan 22, 2025 12:13 PM