

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: REMARKS
Function: Test, Adjust, & Balance
Date: 10/15/2025
Completed By: National TAB

PROJECT
WHATABURGER #1501 MESA, AZ

365 S Power Rd

MESA, AZ 85206

Client

Whataburger Restaurants
300 Concord Plaza Dr
San Antonio, TX 78216

National TAB

Project: WHATABURGER #1501 MESA, AZ

Table Of Contents

Section	Page #
REMARKS	3

Issue List

- EF1 NON-FUNCTIONING
- EXHAUST FANS FOR HOODS NON-FUNCTIONING
- FLEX NOT ATTACHED TO DIFFUSERS
- MOTOR NOT WORKING FOR RTU2



WHATABURGER #1501 MESA, AZ

Project Issue Information

Issue Name : EF1 NON-FUNCTIONING

Description : EF1 is the main exhaust for DINING, it is completely disconnected. Electrical said there's no room in the breaker box to wire it, but will try to run it with an extension cord. UPDATE: Now wired, but no speed controller installed yet. Unit not on.

Created By : National TAB **Assigned To :** National TAB - Brianna Biggs

Status : Open

Priority : Urgent **Asset Tag :** EF1

Originated Date : 10/15/2025 - Christine Weale - National TAB



WHATABURGER #1501 MESA, AZ

Project Issue Information

Issue Name : EXHAUST FANS FOR HOODS NON-FUNCTIONING
Description : KEF1 & 2 appear to be wired correctly, however, no power is going to the hoods or the fans. GC & Electrician notified, still not on by EOD 10/15.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Urgent **Asset Tag :** KITCHEN EXHAUST2
Originated Date : 10/16/2025 - Christine Weale - National TAB



WHATABURGER #1501 MESA, AZ

Project Issue Information

Issue Name : FLEX NOT ATTACHED TO DIFFUSERS
Description : RTU1 GRD-4 & RTU2 GRD-4 flex is not secured to the diffuser's collar. Pulled over collar manually while reading flow for RTU1 to get estimated measurement. Sup and PM aware of issue, est. date for fix: 10/16.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Medium **Asset Tag :** RTUS1
Originated Date : 10/16/2025 - Christine Weale - National TAB



WHATABURGER #1501 MESA, AZ

Project Issue Information

Issue Name : MOTOR NOT WORKING FOR RTU2
Description : No update on a motor replacement from Aeon. RTU2 arrived from factory not working. RTU2 is the larger unit, for DINING area.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Urgent **Asset Tag :** RTU2
Originated Date : 10/15/2025 - Christine Weale - National TAB