




06-03-24 FREDDY'S - DERBY, KS (DERBY) - RENEW

**Project Issue Information**

**Issue Name :** Rtu refrigerant lines iced up  
**Description :** During preventative maintenance I found what seems to be the newest rtu(rtu on the very left) iced up or frosted up on the refrigerant lines. Middle thermostat in office is also only one not meeting tstat temp.  
**Created By :** National TAB **Assigned To :** National TAB - Kyle Henry  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 06/04/2024 - Kyle Henry - National TAB

Project Issue File Details



26598E8D\_C911\_4851\_8493  
\_BC0595B24467.jpeg



2E5714BD\_39C9\_4287\_A887  
\_C268F92E1EC4.jpeg