

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: PUNCHLIST
Function: Test, Adjust, & Balance
Date: 10/01/2025
Completed By: National TAB

PROJECT
09-22-25 QT #0579 OMAHA, NE

1704 SOUTH 72ND STREET

OMAHA, NE

Client

QUIKTRIP
4705 SOUTH 129TH EAST AVENUE
TULSA, OK 74134

National TAB

Project: 09-22-25 QT #0579 OMAHA, NE

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- EF2: Missing Damper
- EF2: Speed Controller not Functional
- RTs: No power to thermostats
- RTUs: Dirty Filters



09-22-25 QT #0579 OMAHA, NE

Project Issue Information

Issue Name : EF2: Missing Damper
Description : The damper for the grille above the combi-oven is missing. Unable to balance airflow to design amount.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** EF2
Originated Date : 09/26/2025 - Kalen Kemp - National TAB


Project Issue File Details



09/26/2025



09/26/2025



09/26/2025



09-22-25 QT #0579 OMAHA, NE

Project Issue Information

Issue Name : EF2: Speed Controller not Functional
Description : The speed controller for EF2 does not work. The screws to the cover plate are worn and was unable to remove cover. Could not access min. position dial. Unable to balance fan to proper airflow.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** EF2
Originated Date : 09/26/2025 - Kalen Kemp - National TAB

Project Issue File Details



09/26/2025



09-22-25 QT #0579 OMAHA, NE

Project Issue Information

Issue Name : RTs: No power to thermostats
Description : There is no power to the thermostats inside of the RTUs. The cover is off of the thermostat inside of RT-2.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :**
Originated Date : 09/26/2025 - Kalen Kemp - National TAB

Project Issue File Details



09/26/2025



09/26/2025



09/26/2025



09-22-25 QT #0579 OMAHA, NE

Project Issue Information

Issue Name : RTUs: Dirty Filters
Description : The filters in the RTUs are dirty. The inside of the filter compartment is very dirty as well. Recommend Cleaning.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 09/26/2025 - Kalen Kemp - National TAB

Project Issue File Details



09/26/2025



09/26/2025



09/26/2025