

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 12/09/2024
Completed By: National TAB

PROJECT
12-09-24 CULVERS ALBERTVILLE, AL

500 Mathis Mill RD.

Albertville, AL 35951

Client

Captive-Aire Region #60

National TAB

Project: 12-09-24 CULVERS ALBERTVILLE, AL

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- PRV-1 BACKDRAFT DAMPER
- PRV-2



12-09-24 CULVERS ALBERTVILLE, AL

Project Issue Information

Issue Name : PRV-1 BACKDRAFT DAMPER
Description : GRAVITY DAMPER IS NOT INSTALLED IN FAN DUCT DROP AS PER PLAN. RECOMMEND HAVING MECHANICAL INSTALL DAMPER AS PER PLAN. SEE M204>"PRV-1 Restroom : SELECTED OPTIONS AND ACCESSORIES".
Created By : National TAB **Assigned To :** National TAB - Kristopher Passley
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/10/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/10/2024



12-09-24 CULVERS ALBERTVILLE, AL

Project Issue Information

Issue Name : PRV-2
Description : FAN IS RAMPING UP AND DOWN CONTINUOUSLY WHEN ON. TROUBLESHOOTING WITH CAPTIVEAIRE TECH SUPPORT WAS UNSUCCESSFUL. RECOMMEND ELECTRICIAN CHECK FAN WIRING AND MOTOR FOR ISSUES.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/10/2024 - Kristopher Passley - National TAB

Project Issue File Details



12/10/2024