

**Report By:**

**National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246**

**NATIONAL**

**TAB**

Comfort. Under control.

**Report: Deficiency List  
Function: Test, Adjust, & Balance  
Date: 8/8/2022**

**PROJECT  
08-08 FIVE GUYS - BROOKLYN, OH**

4824 RIDGE RD

BROOKLYN, OH 44144

**Client**

Wholesome Burger, LLC  
15020 Detroit Ave  
  
Lakewood, OH 44107

# National TAB

Project: 08-08 FIVE GUYS - BROOKLYN, OH

## Table Of Contents

Section	Page #
Issue Data	3




Comfort. Under control.

## 08-08 FIVE GUYS - BROOKLYN, OH

### Project Issue Information

**Issue Name :** Construction filters are in both RTUs  
**Description :** These filters need to be replaced with final filters  
**Created By :** National TAB **Assigned To :** National TAB - Alec Lewis  
**Status :** Open  
**Originated Date :** 08/08/2022 - Ian Fuller - National TAB

#### Project Issue File Details



FuselT856c23495e004fff880b6fa  
7887b3a46.jpeg



Comfort. Under control.

## 08-08 FIVE GUYS - BROOKLYN, OH

### Project Issue Information

**Issue Name :** EF#1 grease cup not installed

**Description :** Grease cup is on the roof next to fan just not installed

**Created By :** National TAB

**Assigned To :** National TAB - Will Turnbough

**Status :** Open

**Originated Date :** 08/08/2022 - Ian Fuller - National TAB

#### Project Issue File Details



FuselT695f54990d994494a2a1f5  
b0e0275edf.jpeg



Comfort. Under control.

## 08-08 FIVE GUYS - BROOKLYN, OH

### Project Issue Information

**Issue Name :** EF#1 not fully secured to curb

**Description :** There are no screws to prevent the fan from leaning back on its hinges.

**Created By :** National TAB

**Assigned To :** National TAB - Will Turnbough

**Status :** Open

**Originated Date :** 08/08/2022 - Ian Fuller - National TAB

#### Project Issue File Details



FuselT6af2ed6ac4ef4e9abd1482  
820924ce52.jpeg



Comfort. Under control.

## 08-08 FIVE GUYS - BROOKLYN, OH

### Project Issue Information

**Issue Name :** RTU#1 fan motor not starting after power disconnect

**Description :** RTU#1 was running, power was cut off at disconnect when turned back on motor will not start but the compressor still runs. Belimo board says unoccupied although thermostat says it's in occupied. When test button is pressed down motor is getting power. RTU is currently off.


**Created By :** National TAB

**Assigned To :** National TAB - Alec Lewis

**Status :** Open

**Originated Date :** 08/08/2022 - Ian Fuller - National TAB


#### Project Issue File Details



FuseITb637f3588d8b4b768b7ae  
fbade0fd323.jpeg



FuseITad55b484797c435f93efc4b  
6e13d0245.jpeg



FuseITd3ff68d786b9401c8f7720e  
f346ae027.jpeg