

Issue List

- EF1 mop fan does not run
- Grease spill on roof
- PRV1 loud rattle when trying to lift fan
- PRV1/PRV2 grease plug missing
- PRV3 restroom exhaust does not run
- RTU2 motor pulley seized



09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : EF1 mop fan does not run
Description : EF1 for the mop sink was found not running. Typically there is a switch for the unit but there was no switch to be found. Recommend replacing the fan.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB


Project Issue File Details



Exhaustfan
09/29/2023



Unitlabel
09/29/2023



Motor(2)
09/29/2023



09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : Grease spill on roof
Description : PRV1 grease spout was found out of the grease trap on the roof. Tech has corrected but there is significant grease leakage on the roof as a result. Recommend having it cleaned for safety.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB

Project Issue Response Details

- **09/29/2023 National TAB - Jacob Davidson**
 - Added pic



IMG_5055
09/29/2023



09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : PRV1 loud rattle when trying to lift fan
Description : When trying to lift up the fan to get pressure, the fan made a very loud rattling and grinding noise. Recommend having the fan adjusted so that it can be lifted up.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB

Project Issue File Details

- 1. [Open](#) IMG_5135.MOV
09/29/2023



09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : PRV1/PRV2 grease plug missing
Description : Grease plug is missing from both hood exhaust fans which can allow grease to fall onto the roof. Recommend replacing the grease plugs.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB

Project Issue File Details



PRV1
09/29/2023



PRV2
09/29/2023

09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : PRV3 restroom exhaust does not run
Description : PRV3 for restroom exhaust was found not running with the disconnect on. Recommend replacing the fan motor.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB

Project Issue Response Details

- **09/29/2023 National TAB - Jacob Davidson**
 - Added pictures



IMG_5140
09/29/2023



IMG_5068
09/29/2023



IMG_5067
09/29/2023



09-25-23 CULVERS BLUE SPRINGS,MO REVIVE

Project Issue Information

Issue Name : RTU2 motor pulley seized
Description : Motor pulley is seized and tech is unable to move the pulley in order to increase unit speed. Recommend having MC loosen the pulley to be freely adjusted.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 09/29/2023 - Jacob Davidson - National TAB

Project Issue File Details



Pulley
09/29/2023