

Report By:

National TAB



Report: PUNCH-LIST

Function: Test, Adjust, & Balance

Date: 09/09/2025

Completed By: National TAB

PROJECT

Fifth Third Bank (Union, KY)

Lot 11 Sec 2 Union Promenade

Union, KY 41091

Client

Mechanical Optimizers

2145 Patterson Street

Cincinnati, OH 45214

National TAB

Project: Fifth Third Bank (Union, KY)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- EF Speed Controls
- RTU-2: Diffuser 10 damper



Fifth Third Bank (Union, KY)

Project Issue Information

Issue Name : EF Speed Controls
Description : The exhaust fans need new speed controls installed to be balanced
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 09/10/2025 - Corey Dick - National TAB



Fifth Third Bank (Union, KY)

Project Issue Information

Issue Name : RTU-2: Diffuser 10 damper
Description : A damper needs to be installed on diffuser 10 to control airflow separate of diffuser 9
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : [Medium](#) **Asset Tag :**
Originated Date : 09/10/2025 - Corey Dick - National TAB