

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: TAB Punch-List
Function: Test, Adjust, & Balance
Date: 07/10/2025
Completed By: National TAB

PROJECT

Conner HS Fieldhouse (Hebron, KY)

3310 Cougar Path

Hebron, KY 41048

Client

Tri-State Mechanical

4498 Petersburg Rd

Burlington, KY 41005

National TAB

Project: Conner HS Fieldhouse (Hebron, KY)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- ERV 1 Exhaust
- ERV 1 Exhaust Dampers
- ERV 2 BALANCE DAMPERS
- Weight room Damper



Conner HS Fieldhouse (Hebron, KY)

Project Issue Information

Issue Name : ERV 1 Exhaust
Description : Restrictive ductwork on the exhaust duct for restroom C7 preventing exhaust flow.
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/10/2025 - Gabe Merk - National TAB

Project Issue File Details



07/10/2025

Project Issue Response Details

- **07/11/2025 National TAB - Gabe Merk**
 - Issue has been resolved. Reread/balance flow on next trip.




Conner HS Fieldhouse (Hebron, KY)

Project Issue Information

Issue Name : ERV 1 Exhaust Dampers
Description : Two exhaust grilles on ERV 1 are missing dampers. Unable to distribute flow to other individual grilles.
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/10/2025 - Gabe Merk - National TAB

Project Issue File Details






Conner HS Fieldhouse (Hebron, KY)

Project Issue Information

Issue Name : ERV 2 BALANCE DAMPERS
Description : ERV 2 Balance damper jammed. See attached photo highlighted in orange. Additional balance damper install likely needed in location highlighted in red.
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/10/2025 - Gabe Merk - National TAB

Project Issue File Details



Project Issue Response Details

- **07/11/2025 National TAB - Gabe Merk**
 - Balance damper opened. Additional Balance damper needed to reduce flow to C13.



Conner HS Fieldhouse (Hebron, KY)

Project Issue Information

Issue Name : Weight room Damper
Description : A damper will be needed in the weight room in order to distribute flow to the remaining duct branches.
Created By : National TAB **Assigned To :** National TAB - Nick Payne
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/10/2025 - Gabe Merk - National TAB

Project Issue File Details

