

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: TAB Punch-List**  
**Function: Test, Adjust, & Balance**  
**Date: 07/10/2025**  
**Completed By: National TAB**

# PROJECT

## Conner HS Fieldhouse (Hebron, KY)

3310 Cougar Path

Hebron, KY 41048

### Client

Tri-State Mechanical

4498 Petersburg Rd

Burlington, KY 41005

# National TAB

Project: Conner HS Fieldhouse (Hebron, KY)

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- ERV 1 Exhaust
- ERV 1 Exhaust Dampers
- ERV 2 BALANCE DAMPERS
- Weight room Damper



## Conner HS Fieldhouse (Hebron, KY)

### Project Issue Information

**Issue Name :** ERV 1 Exhaust  
**Description :** Restrictive ductwork on the exhaust duct for restroom C7 preventing exhaust flow.  
**Created By :** National TAB                      **Assigned To :** National TAB - Nick Payne  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/10/2025 - Gabe Merk - National TAB

#### Project Issue File Details



07/10/2025




### Conner HS Fieldhouse (Hebron, KY)

#### Project Issue Information

**Issue Name :** ERV 1 Exhaust Dampers  
**Description :** Two exhaust grilles on ERV 1 are missing dampers. Unable to distribute flow to other individual grilles.  
**Created By :** National TAB                      **Assigned To :** National TAB - Nick Payne  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/10/2025 - Gabe Merk - National TAB

#### Project Issue File Details






### Conner HS Fieldhouse (Hebron, KY)

#### Project Issue Information

**Issue Name :** ERV 2 BALANCE DAMPERS  
**Description :** ERV 2 Balance damper jammed. See attached photo highlighted in orange. Additional balance damper install likely needed in location highlighted in red.  
**Created By :** National TAB                      **Assigned To :** National TAB - Nick Payne  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/10/2025 - Gabe Merk - National TAB

#### Project Issue File Details





### Conner HS Fieldhouse (Hebron, KY)

#### Project Issue Information

**Issue Name :** Weight room Damper  
**Description :** A damper will be needed in the weight room in order to distribute flow to the remaining duct branches.  
**Created By :** National TAB                      **Assigned To :** National TAB - Nick Payne  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/10/2025 - Gabe Merk - National TAB

#### Project Issue File Details

