

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Punchlist**  
**Function: Test, Adjust, & Balance**  
**Date: 12/16/2025**  
**Completed By: National TAB**

# PROJECT

## 12-15-25 CULVERS BUSHNELL, FL (DOAS)

1942 W C 48

BUSHNELL , FL 33513

**Client**

Captive-Aire Region #60

# National TAB

Project: 12-15-25 CULVERS BUSHNELL, FL (DOAS)

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- Employee Bathroom Damper




**12-15-25 CULVERS BUSHNELL, FL (DOAS)**

**Project Issue Information**

**Issue Name :** Employee Bathroom Damper  
**Description :** The damper controlling the diffuser in the employee bathroom off the kitchen is loose, and will not remain in the position needed to lower airflow to design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 12/15/2025 - Jackson Gunnels - National TAB

Project Issue File Details



12/15/2025



12/15/2025