

## Issue List

- DOAS Clogged Filter active fault
- KEF2 no hinge kit installed
- KEF3 not powered



## 10-16-23 FREDDYS - PROVO, UT

### Project Issue Information

**Issue Name :** DOAS Clogged Filter active fault  
**Description :** The DOAS unit HMI is showing a clogged filter active fault. Unit was checked and the filters are new. GC is aware and CAS is scheduled to come out and address issues with DOAS with Morris Controls. Fan is running for TAB purposes.

**Created By :** National TAB                      **Assigned To :** National TAB - Jacob Davidson

**Status :** Open

**Originated Date :** 10/16/2023 - Jacob Davidson - National TAB

#### Project Issue File Details



IMG\_5360  
10/16/2023



## 10-16-23 FREDDYS - PROVO, UT

### Project Issue Information

**Issue Name :** KEF2 no hinge kit installed  
**Description :** KEF2 has no hinge kit installed to lean the fan back for cleaning. The hinge kit was installed on KEF3 for the dishhood fan where it is not needed. Recommend MC remove the hinge kit from KEF3 and put it on KEF2.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jacob Davidson  
**Status :** Closed  
**Originated Date :** 10/16/2023 - Jacob Davidson - National TAB

#### Project Issue Response Details

- **10/17/2023 National TAB - Jacob Davidson**
  - Units had their hinge kits swapped over to correct curbs. Closing ticket
- **10/16/2023 National TAB - Jacob Davidson**
  - Added photos



IMG\_5370  
10/16/2023



IMG\_5367  
10/16/2023




## 10-16-23 FREDDYS - PROVO, UT

### Project Issue Information

**Issue Name :** KEF3 not powered  
**Description :** KEF3 is not powered and needs to be interlocked with the dishwasher. GC is aware and is going to try to get someone here to get the fan running.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jacob Davidson  
**Status :** Closed  
**Originated Date :** 10/16/2023 - Jacob Davidson - National TAB

#### Project Issue File Details



IMG\_5365  
10/16/2023

#### Project Issue Response Details

- **10/17/2023 National TAB - Jacob Davidson**
  - EC had the fan wired and a breaker needed to be flipped. Unit runs. Closing ticket.