

Issue List

- DOAS Clogged Filter active fault
- DOAS kitchen HMI blank screen
- EF1/EF2 no speed controller



10-16-23 FREDDYS - PROVO, UT

Project Issue Information

Issue Name : DOAS Clogged Filter active fault
Description : The DOAS unit HMI is showing a clogged filter active fault. Unit was checked and the filters are new. GC is aware and CAS is scheduled to come out and address issues with DOAS with Morris Controls. Fan is running for TAB purposes.

Created By : National TAB **Assigned To :** National TAB - Jacob Davidson

Status : Open

Originated Date : 10/16/2023 - Jacob Davidson - National TAB

Project Issue File Details



IMG_5360
10/16/2023



10-16-23 FREDDYS - PROVO, UT

Project Issue Information

Issue Name : DOAS kitchen HMI blank screen
Description : Kitchen HMI for DOAS unit is blank and cannot be controlled. GC is aware and CAS is scheduled to come look at the DOAS unit to address the fault messages with Morris controls company..
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 10/17/2023 - Jacob Davidson - National TAB

Project Issue File Details



HMIblank
10/17/2023


10-16-23 FREDDYS - PROVO, UT

Project Issue Information

Issue Name : EF1/EF2 no speed controller
Description : EF1 and EF2 for the restrooms are high on flow and have no speed controller to reduce the speed of the fans. Recommend having the responsible party add them to the fans to reduce the airflow.
Created By : National TAB **Assigned To :** National TAB - Jacob Davidson
Status : Open
Originated Date : 10/17/2023 - Jacob Davidson - National TAB

Project Issue Response Details

- **10/17/2023 National TAB - Jacob Davidson**
 - Added pictures



IMG_5383
10/17/2023



IMG_5378
10/17/2023