

# TAB PUNCH LIST CFA 04968

Prepared by Will T

May 22, 2024

## Description

3 tasks in this report.

## Contents

#7 Hood 1 Missing Filter.....	2
#6 Hood 1L Dented .....	4
#5 Remote Sensors Not Labeled .....	6

## #7 Hood 1 Missing Filter

**Status**

Open

**Start Date**

Apr 10, 2024

**Type**

Planned Work

**Created**

Apr 10, 2024 4:34 PM  
ianf@nationaltab.com

**Description**

One of the hood filters could not be located during balancing. Filters were moved back and forth between hoods 1 and 2, and the fans were tested individually so that balance setpoints could be found.

**Last Updated**

May 22, 2024 9:39 AM

**Photos**

L04968\_Pines & 160th FSU (FL)

15901 Pines Boulevard, Pembroke Pines, Florida

L1020004968



9-Mar 26 2024 03\_24pm-Nb2Y

**John Cardona**

Mar 26, 2024 2:24 PM

## #6 Hood 1L Dented

**Status**

Open

**Start Date**

Apr 10, 2024

**Type**

Planned Work

**Created**

Apr 10, 2024 4:33 PM  
ianf@nationaltab.com

**Description**

There is a large dent in Hood-1L. This is not expected to cause performance issues

**Last Updated**

May 22, 2024 9:38 AM

**Photos**



4968 Fryer and Hoods  
**John Cardona**  
Apr 11, 2024 2:40 PM



4968 Fryers and Hoods 2  
**John Cardona**  
Apr 11, 2024 2:40 PM



**L04968\_Pines & 160th FSU (FL)**

15901 Pines Boulevard, Pembroke Pines, Florida

L1020004968



20240328\_161454\_photo

**John Cardona**

Mar 28, 2024 3:14 PM

---